
OC CURVES - AQL = 0.25
PERCENT OF LOTS EXPECTED TO BE ACCEPTED, Pa
100
90
80
70
60
50
40
30
20
10
0
0
0.5
1.0
1.5
2.0
2.5
3.0
3.5
4.0
P,O
N
M
R
QUALITY OF SUBMITTED LOTS, 100p
(In percent defective or defects per hundred units)


OC CURVES - AQL = 0.25
PERCENT OF LOTS EXPECTED TO BE ACCEPTED, Pa
100
90
80
70
60
50
40
30
20
10
0
0
0.2
0.4
0.6
0.8
1.0
1.2
1.4
1.6
U
T
S
QUALITY OF SUBMITTED LOTS, 100p
(In percent defective or defects per hundred units)