
OC CURVES - AQL = 0.40
PERCENT OF LOTS EXPECTED TO BE ACCEPTED, Pa
100
90
80
70
60
50
40
30
20
10
0
0
0.8
1.6
2.4
3.2
4.0
4.8
5.6
6.4
L
M
N,P
Q
QUALITY OF SUBMITTED LOTS, 100p
(in percent defective or defects per hundred units)


OC CURVES - AQL = 0.40
PERCENT OF LOTS EXPECTED TO BE ACCEPTED, Pa
100
90
80
70
60
50
40
30
20
10
0
0
0.3
0.6
0.9
1.2
1.5
1.8
2.1
2.4
R
S
T
U
QUALITY OF SUBMITTED LOTS, 100p
(in percent defective or defects per hundred units)