
OC CURVES - AQL = 1.0
PERCENT OF LOTS EXPECTED TO BE ACCEPTED, Pa
100
90
80
70
60
50
40
30
20
10
0
0
2.0
4.0
6.0
8.0
10.0
12.0
14.0
16.0
P
N
M
K,L
J
QUALITY OF SUBMITTED LOTS, 100p
(In percent defective or defects per hundred units)


OC CURVES - AQL = 1.0
PERCENT OF LOTS EXPECTED TO BE ACCEPTED, Pa
100
90
80
70
60
50
40
30
20
10
0
0.5
1.0
1.5
2.0
2.5
3.0
3.5
4.0
4.5
U
T
S
R
Q
QUALITY OF SUBMITTED LOTS, 100p
(In percent defective or defects per hundred units)