
OC CURVES - AQL = 4.0
PERCENT OF LOTS EXPECTED TO BE ACCEPTED, Pa
100
90
80
70
60
50
40
30
20
10
0
0
5.0
10.0
15.0
20.0
25.0
30.0
35.0
40.0
K,L
J
G
D
N
M
QUALITY OF SUBMITTED LOTS, 100p
(In percent defective or defects per hundred units)


OC CURVES - AQL = 4.0
PERCENT OF LOTS EXPECTED TO BE ACCEPTED, Pa
100
90
80
70
60
50
40
30
20
10
0
3.0
4.0
5.0
6.0
7.0
8.0
9.0
10.0
11.0
P
Q
R
S
T
U
QUALITY OF SUBMITTED LOTS, 100p
(In percent defective or defects per hundred units)