
℄ OF SPINDLE
FACE OF GRINDING DISCS
W
A – A
E
DIRECTION OF ROTATION
WORK
CONVEYOR
A
A
DIRECTION OF CONVEYOR
D
D+2
ANY METHOD OF FEEDING PARTS TO BE GROUND MAY BE USED.
E