Figure 6 to Subpart A of Part 1211—Edge Sensor Normal Operation Test



Figure 7 to Subpart A of Part 1211—PUNCTURE PROBE