
OC CURVES - AQL = 0.65
PERCENT OF LOTS EXPECTED TO BE ACCEPTED, Pa
100
90
80
70
60
50
40
30
20
10
0
0
1.2
2.4
3.6
4.8
6.0
7.2
8.4
9.6
K
M,N
L
P
O
QUALITY OF SUBMITTED LOTS, 100p
(In percent defective or defects per hundred units)


OC CURVES - AQL = 0.65
PERCENT OF LOTS EXPECTED TO BE ACCEPTED, Pa
100
90
80
70
60
50
40
30
20
10
0
0
0.3
0.6
0.9
1.2
1.5
1.8
2.1
2.4
R
S
T
U
QUALITY OF SUBMITTED LOTS, 100p
(In percent defective or defects per hundred units)