
OC CURVES - AQL = 2.5
PERCENT OF LOTS EXPECTED TO BE ACCEPTED, Pa
100
90
80
70
60
50
40
30
20
10
0
0
4.0
8.0
12.0
16.0
20.0
24.0
28.0
32.0
F
J,K
L
M
N
QUALITY OF SUBMITTED LOTS, 100p
(In percent defective or defects per hundred units)


OC CURVES - AQL = 2.5
PERCENT OF LOTS EXPECTED TO BE ACCEPTED, Pa
.00
90
80
70
60
50
40
30
20
10
0
2.0
3.0
4.0
5.0
6.0
7.0
8.0
9.0
10.0
O
P
R
S
T
U
QUALITY OF SUBMITTED LOTS, 100p
(In percent defective or defects per hundred units)