
OC CURVES - AQL = 6.5
PERCENT OF LOTS EXPECTED TO BE ACCEPTED, Pa
QUALITY OF SUBMITTED LOTS, 100p
(In percent defective or defects per hundred units)
L
K
J
H
E
B


OC CURVES - AQL = 6.5
PERCENT OF LOTS EXPECTED TO BE ACCEPTED, Pa
QUALITY OF SUBMITTED LOTS, 100p
(In percent defective or defects per hundred units)
M
N
P
Q
R
S