
MAP OF QUATERNARY TRACES
POINT OF NEAREST APPROACH TO NUCLEAR POWER PLANT
NUCLEAR POWER PLANT LOCATION
CONTROL WIDTH OF FAULT
WIDTH OR ZONE REQUIRING DETAILED FAULTING INVESTIGATIONS (1 TO 4 TIMES CONTROL WIDTH)
CONTROL WIDTH OF FAULT
10 MILES
10 MILES