

Figure 56.30–10(b)—Methods of Attachment