THRESHOLD LIMIT VALUES OF AIRBORNE CONTAMINANTS FOR CONSTRUCTION

Substance	CAS No.[d]	ppm [a*]	mg/m^3 [b]	Skin designation
* *	*	*	*	* *
Silica, crystalline, respirable dust				
Cristobalite; see 1926.1153	14464-46-1			
Quartz; see 1926.1153[5]	14808-60-7			
Tripoli (as quartz); see 1926.1153[5]	1317-95-9			
Trydimite; see 1926.1153	15468-32-3			
* *	*	*	*	* *

MINERAL DUSTS

SILICA:	250[(k)]
Crystalline	
Quartz. Threshold Limit calculated from the formula [(p)]……	% SiO2+5
* * * * *	* *