
OC CURVES – AQL = 0.25
PERCENT OF PORTIONS OF PRODUCTION EXPECTED TO BE ACCEPTED, Pa
100
90
80
70
60
50
40
30
20
10
0
Reduced
Normal
Tightened
0
5.0
10.0
15.0
20.0
25.0
30.0
35.0
QUALITY OF SUBMITTED PORTIONS OF PRODUCTION, 100p
(Defects per hundred units)