Figure 7 to Subpart A of Part 1211—PUNCTURE PROBE