

Figure 3. Circuit for Measuring PLC Control Signal Power in Standby Mode