

DISTRIBUTION ARMS

Figure 1

No knot shall exceed $\frac{3}{4}$ " for close grain
and 1" for dense material in this top section


TRANSMISSION ARMS
POLE MOUNTING HOLE ZONE

Figure 2

No knot shall exceed a diameter of 1"
for close grain, or $1\frac{1}{4}$ " for dense
grain, in these two sections.

