



*** The engine and ATTCS failed time interval must be no shorter than the time interval from the point of simultaneous engine and ATTCS failure to a height of 400 feet used to comply with 125.2(b) for ATTCS use during takeoff.**