

$$\text{Maximum Rate} = \text{Space Factor} \times \text{Net Cost of a Bare Pole} \times \text{Carrying Charge Rate}$$

Where

$$\text{Space Factor} = \frac{\text{Space Occupied by Attachment}}{\text{Total Usable Space}}$$