

$\dot{E}_c^{k=i}(T_j) = \frac{\dot{Q}_c^{k=i}(T_j)}{EER^{k=i}(T_j)}$ , the electrical power input required by the test unit when operating

at a compressor speed of  $k = i$  and temperature  $T_j$ , W.