


## DISTRIBUTION ARMS

Figure 1

No knot shall exceed  $\frac{3}{4}$ " for close grain  
and 1" for dense material in this top section

Pole mounting hole



No knot shall exceed 1" for close  
grain and  $1\frac{1}{4}$ " for dense material

Brace bolt hole  
(included in center section)