

$$x_{\text{NOdry}} = \frac{x_{\text{NOmeas}}}{1 - x_{\text{H}_2\text{Omeas}}}$$

Eq. 1065.655-16