

$$x_{\text{NO}_2 \text{dry}} = \frac{x_{\text{NO}_2 \text{meas}}}{1 - x_{\text{H}_2\text{O NO}_2 \text{meas}}}$$

Eq. 1065.655-17