



WHEEL DEFECT GAUGE

Method of gauging worn flanges.



Method of gauging shelled and flat spots.



Method of gauging broken rims.

