




PMT Entrance  
Window Completely  
Covered



(a) Zero-Signal Level Test



(b) Clear-Air or 0% Opacity Test



(c) Optical Filter Test (simulated opacity values)

\*Tests shall be performed with no ambient or stray light reaching the detector.

Figure Aml-VI. Test Configuration for Technique 1.