



Notes:

- ① Refer to appropriate cable specifications for tip and ring conductor identification.
- ② Connections to be made in accordance with the manufacturer's instructions.
- ③ Connections to be made in accordance with 7 CFR 1755.200, "RUS standard for splicing copper and fiber optic cables."

RURAL TELECOMMUNICATIONS CONSTRUCTION PRACTICES
BURIED PLANT CONDUCTOR POLARITY DIAGRAM

Scale: NTS

March 2001

815-1