

Table I-7 -- Flammability Test

Test Method	Criteria for Passing Test
<ol style="list-style-type: none">1. Vertically suspend a 19.7-inch (500-mm) length of strapping supporting a 220.5-lb (100-kg) weight;2. Use a butane or propane burner with a 3-inch (76-mm) flame;3. Direct the flame to an edge of the strapping at a distance of 1 inch (25mm);4. Remove the flame after 5 seconds; and5. Wait for any flames on the positioning strap to stop burning.	<p>Any flames on the positioning strap must self-extinguish.</p> <p>The positioning strap must continue to support the 220.5-lb (100-kg) mass.</p>