

$$x_{\text{THCdry}} = \frac{x_{\text{THCmeas}}}{1 - x_{\text{H}_2\text{O}}\text{THCmeas}}$$

Eq. 1065.655-18