

$$V_{CO_2k} = \frac{(P_{CO_2k})_{k+1} \cdot Q_{k+1}}{100} \quad \text{[Eq. C-12]}$$