FIGURE 8

VIBRATION TEST FOR UNPACKAGED HOUSINGS